

2–YEAR INUNDATION

50–YEAR INUNDATION

Penfield & Smith
Engineering · Surveying · Planning
· Construction Management ·

N

1" = 50'

BURNED AND BULKED
MALIBU BLUFFS
CREEK CROSSING
SANTA MONICA MOUNTAINS

MALIBU, CALIFORNIA

13638.07 EXHIBIT–CREEK CROSSING.DWG

EXHIBIT BB-22